Version history - Regio Ardo/Eedo

This document summarises the software updates for Regio Ardo/Eedo.

Version 2.2-1-01

October 19th, 2026

Release of version 2.2-1-01 which addresses numerous small issues please see below for details.

- *TP#22425* - Regio Ardo - Solved issues with scheaduling
- *TP#26370/23640* - Regio Eedo - Added Regio Shut down and Bypass in Modbus
- *TP#27651* - Regio - Fixed issues where no manual alarm triggered when outputs are Manual Off
- *TP#27654* - Regio Eedo - Expanded usage of relay outputs
- *TP#31713* - Regio Ardo + ED-RU-DOS - Fixed issue where display shows Sun blinds symbol instead of open window
- *TP#42707* - Regio Ardo/Eedo - Fixed Issues with Room 2 in At2
- *TP#42743/48029* - Regio Ardo with ED-RU-F - When fan is stopped manually, cooling output still opens or can be opened - issue fixed
- *TP#45340* - Regio Ardo - Fixed issue where the valves and the fan do not activate
- *TP#45561/48473* - Regio Ardo - 2-zone with ED-RU-DFO - fixed issue with fan behaviour
- *TP#45562* - Regio Ardo + ED-RU-DFO - Fixed issues with Fan blocks in display in manual mode
- *TP#45958* - Regio Eedo + ED-RUD - Fixed issue with ELA in tool
- *TP#46686* - Regio Ardo/Eedo + RUX-THCVP-D - Fixed Application Tool 2 issues with CO2 and PIR settings not being visible
- *TP#47016* - Regio Ardo + RUX - fixed issues with default mode / setpoint
- *TP#47022/47029* - Regio Ardo + RUX - Mode to ON in the RUX the unit stays OFF when remote control is Unoccupied - fixed several issues with Modes not syncing btw. units
- *TP#47491* - Regio Ardo + RUX - 2-zone, several issues solved with setpoint adjustment, mode menu
- *TP#48473/45561* - Regio Ardo + ED-RU-DFO - fixed issue where it was not possible to use the fan button to change fan speed
- *TP#48962* - Regio Ardo/Eedo + RUX - fixed issues displaying CO2 level on RUX-...-D

Version 2.2-1-00

December 17th, 2025

Support for Regio RUX, improvements and added functionality.
See below for details.

- Support for Regio RUX Room Unit (*TP#28311*)
  Added support for the new Regio RUX room unit.
- Support for Humidity control (*TP#45086*)

Added control loop for Humidity, works same way as for CO2.

- Regio Ardo/Eedo - Tooltip AT2 missing modbus address (*TP#40711*)
  Improved information in tooltip Application tool 2.
- Regio Ardo 2 rooms: CO2 sensor is not read for Room 2 (*TP#41070*)
  Correction in CO2 sensor functionality for room 2.
- Regio Ardo 2 rooms: "room unit not connected" false alarm (*TP#41071*)
  Solved issue with false alarm.
- Application Tool 2 error message in section Modbus room unit (*TP#41075*)
  Solved issue with missing heading in Application tool 2.
- Regio Ardo - Cooling valve settings room 2 (*TP#42162*)
  Solved issue with missing settings in Application tool 2.
- Application Tool Regio 2.1-1-00 Actual values are not displayed (*TP#42682*)
  Solved issue with actual values for Heating and Cooling missing in Application tool 2.
- Regio Eedo2.1-1-00 does not follow time scheduler (*TP#45495*)
  Solved issue where state was not changed according to the schedule set up in the time scheduler.

Version 2.2-1-00

Improvements and added functionality.
See below for details.

- Improved BACnet support (*TP#27631*)
  Support for renaming BACnet objects.
- Improved Afterblow function (*TP#35619*)
  Solved an issue where afterblow does not functon with electric heater and change-over mode set to Cooling.
- Improved Afterblow function (*TP#27650*)
  Solved an issue where afterblow can be overridden by manual fan settings.
- Add removable walls function for Regio Eedo (*TP#31835*)
  Possibility to connect five controllers (forming one zone) whereof one acting as a master controlling the other four.
- Support for generic Room Units (*TP#27628*)
  Connect room units from other brands via modbus.
- Documentation Improvements (*TP#22115*)
  Merged the Manual for Eedo and Ardo. Clarified when it is needed to fill in ELA.

© AB Regin. All rights reserved.