



Software Revision History, Regio Ardo/Eedo

Version: Regio Ardo/Eedo 2.2-1-00

Description: Support for Regio RUX, improvements and added functionality

See below for details

Support for Regio RUX Room Unit (#28311)

Added support for the new Regio RUX room unit

Support for Humidity control (#45086)

Added control loop for Humidity, works same way as for CO₂

Regio Ardo/Eedo - Tooltip AT2 missing modbus address (#40711)

Improved information in tooltip Application tool 2

Regio Ardo 2 rooms: CO₂ sensor is not read for Room 2 (#41070)

Correction in CO₂ sensor functionality for room 2"

Regio Ardo 2 rooms: "room unit not connected" false alarm (#41071)

Solved issue with false alarm

Application Tool 2 error message in section Modbus room unit (#41075)

Solved issue with missing heading in Application tool 2

Regio Ardo - Cooling valve settings room 2 (#42162)

Solved issue with missing settings in Application tool 2

Application Tool Regio 2.1-1-00 Actual values are not displayed (#42682)

Solved issue with actual values for Heating and Cooling missing in Application tool 2

AB Regin

Tel: +46 31 720 02 00 E-mail: info@regin.se www.regincontrols.com

Address: Bangårdsvägen 35 428 36 Kållered





Regio Eedo2.1-1-00 does not follow time scheduler (#45495)

Solved issue where state was not changed according to the schedule set up in the time scheduler

Version: Regio Ardo/Eedo 2.2-1-00

Description: improvements and added functionality

See below for details

Improved BACnet support (#27631)

Support for renaming BACnet objects

Improved Afterblow function (#35619)

Solved an issue where afterblow does not functon with electric heater and change-over mode set to Cooling

Improved Afterblow function (#27650)

Solved an issue where afterblow can be overridden by manual fan settings

Add removable walls function for Regio Eedo (#31835)

Possibility to connect five controllers (forming one zone) whereof one acting as a master controlling the other four.

Support for generic Room Units (#27628)

Connect room units from other brands via modbus.

Documentation Improvements (#22115)

Merged the Manual for Eedo and Ardo.

Clarified when it is needed to fill in ELA

AB Regin

Tel: +46 31 720 02 00 E-mail: info@regin.se www.regincontrols.com Address: Bangårdsvägen 35 428 36 Kållered

